Appendix 3

Site photographs and location plan

Photos, West Millrigg, Wiston CL/10/0152



Photo 1 View westward from B7055 to West Millrigg



Photo 2 View from B7055 to number 2 West Millrigg showing glazed garden building.



Photo 3 Front elevation of garden building and its concrete base, showing proximity to the boundary fence.



Photo 4 An example of unauthorised buildings which have been erected elsewhere at West Millrigg



Photo 5 Section of feature wall at the access to West Millrigg



Photo 6 Looking west when exiting the site onto the B7055.



Photo 7 Glazed garden building and 1.8 metre screen fence.



Photo 8 Looking north-west from rear of number 2 West Millrigg up to the garden building.



Photo 9 Timber fencing, from rear of number 2, West Millrigg looking north



Photo 10 Timber fencing between numbers 1 and 2 West Millrigg.



Photo 11 - 1.8 metre high timber fencing and concrete area associated with garden building.

West Millrig, Wiston

