

## Housing & Technical Resources - Property & Estates

### Property Accessibility Summary

Property Name	John Wright Sports Centre
Property SLPN	3175

Access Element	Comments	Element Rating		
		Poor	Fair	Good
Access to Building	6nr. Disabled car parking spaces to main entrance. Dropped kerbs to car parking and road crossing. Sloped surface from car park to main entrance with level access			√
Entrance Door	Powered main entrance door operated by sensors as personnel approach to door			√
Reception Area	Main reception has lowered desk, induction loops.			√
Door Width Internally	Internal Door widths are suitable for access			√
Accessible Toilet Facilities	Accessible toilet with suitable width to accommodate powered wheelchair			√
Changing places toilet	No Changing places toilet available in property	n/a		
Access to upper floors	Lift compliant with Part M of the regulations. 1400mm x1100mm, door opening size 800mm provided with braiile signage,			√

## Housing & Technical Resources - Property & Estates

### Property Accessibility Summary

Property Name	Coalburn Leisure Centre
Property SLPN	4003

Access Element	Comments	Element Rating		
		Poor	Fair	Good
Access to Building	3 nr. Disabled car parking spaces to main entrance. Signage requires refixed and some repairs to slabs. Dropped kerbs from disabled car parking . Main entrance from car park is sloped.		✓	
Entrance Door	Powered entrance door from top landing, but call point to reception positioned inconveniently		✓	
Reception Area	Main reception has two lowered desk areas.		✓	
Door Width Internally	All doors are min 800mm		✓	
Accessible Toilet Facilities	Accessible toilet with suitable width to accommodate powered wheelchair . Grab rails are not colour coordinated.		✓	
Changin places toilet	No provision	✓		
Access to upper floors	No upper floors			